

# FIELD ENGINEERING BULLETIN

## WY-60 FLYBACK UPGRADE

### DESCRIPTION

This bulletin releases the new Flyback Upgrade Kit for the WY-60 product. The upgrade kit improves overall reliability of the WY-60 Main Board Assembly by replacing the General Instruments RGP5100 diode, which supports G2 (screen voltage), with a UF4007 diode, and replacing the BU406 transistor with a 2SC2898 transistor. The Flyback transformer is also changed in this procedure.

### **SYMPTOMS**

One or more of the following components on the WY-60 Main Board Assembly have failed:

- 1) The General Instruments RGP5100 diode at location D203
- 2) The BU406 Transistor at location Q202
- 3) The Flyback Transformer

## PRODUCTS AFFECTED

WY-60

#### REVISION LEVEL

920064-01 Rev. A

Flyback Upgrade Kit, WY-60

Note: This FEB must be performed by a WYSE Service Center or a WYSE Authorized Service Center. For service in the USA, contact the WYSE RMA Department at 800-626-3160. Customers in all other countries are to contact their local WYSE Service Center.

#### RECOMMENDED PARTS

920064-01 Rev. A

Flyback Upgrade Kit, WY-60

Qty: 1

The Flyback Upgrade Kit contains the following parts:

272032-01 283730-01

Transistor, 2SC2898, (Q202) Diode, UF4007, (D203)

Qty: 1

420016-01

Flyback Transformer, (T202)

Qty: 1

PRODUCT	SOURCE	AUTHORVERIFY	STATUS	FEB REVISION DATE	FEB NUMBER	ACTION PRIORITY	PAGE	-
	ECN-4046	16	FINAL	NOV. 28, 1989	0268	REQUIRED: OPTIONAL SPECIALIDEM: ADVISORY: X	1 of 3	



## FIELD ENGINEERING BULLETIN

## STOCK DISPOSITION

TABLE 1 - Stock and Service Disposition

	LOCA	TION
PART NUMBER	SPARES	SERVICE
920064-01	Stock	Stock

LEGEND		
B STOCK - Continue or start to stock this part.	M REWORK - R - Required rework.	NA - Not applicable.
B PURGE - Purge all stock of this part.	B REWORK - 0 - Optional rework.	B USE NTE (DATE) - Use remaining stock but do not keep past the specific date.

#### **RECOMMENDED TOOLS**

Phillips Screwdriver
Soldering Station
Needlenose Pliers
Diagonal Cutters
Alligator Clips
Insulated Flat Blade Screwdriver - 12 in.

#### INSTRUCTIONS

IMPORTANT:

a. Recommendation — Replace the Main Board Assembly for any

board related problem.

b. If component level repair is desired, follow the steps in this bulletin.

c. Although one or more of the components specified in the instructions below appear to be functioning properly, they must all be replaced.

NOTE:

Before beginning this procedure, familiarize yourself with the following cautions:

a. Handle circuit boards by their edges.

b Follow acceptable ESD precautions when handling circuit boards and components.

c. Be careful not to lift any traces when working on the board.

d. Remove all flux residue.

- 1. Remove the Main Board Assembly from the unit. Refer to the WY-60 Maintenance Manual Page 2-11 for the removal procedure.
- 2. Replace the RGP5100 diode (P/N 283703-01) at location D203 with the new UF4007 diode (P/N 283730-01).

PRODUCT	SOURCE	AUTHORVERIFY	STATUS	FEB REVISION DATE	FEB NUMBER	ACTION PRIORITY	PAGE
WY-60	ECN-4046	J.G.	FINAL	NOV. 28, 1989	0268	REQUIRED OPTIONAL SPECIALOENE ADVISORY X	2 of 3

0268



## FIELD ENGINEERING BULLETIN

- 3. Replace the flyback transformer at location T202 with the new transformer (P/N 420016-01).
- 4. Replace the BU406 transistor (P/N 272000-01) at location Q202 with the new 2SC2898 transistor (P/N 272032-01).

IMPORTANT:

Thermal compound must be used between the transistor, the heat sink, and the insulator to insure good heat transfer at the time the transistor change is implemented.

- 5. Re-assemble the unit.
- 6. Update the schematics and the parts list to reflect the change.

PRODUCT	SOURCE	AUTHOR/VERIFY	STATUS	FEB REVISION DATE	FEB NUMBER	ACTION PRIORITY	PAGE
WY-60	ECN-4046	J.G.	FINAL	NOV. 28, 1989	0268	REQUIRED: OPTIONAL: SPECIALOEM ADVISORY:	<b>3</b> of 3